

Segment #168085

Hydrologically- Connected
Slope(field/Avg) 9.5/9.0%

Does Not Meet

Rating: HIGH

Crown- FM

Berm- FM

Road Drainage-DNM

Cross Culvert-none

